On Track	(	Outstanding Is	ssue	Difficulty				Change		Plan Actual			
Installation	Facility Size	Server	Perm Admin	Temp Admin	Perm Warehouse	Temp Warehouse	Bldg Offered	Bldg Accept	30% Design Review	Gov repair Complete	Constr. % Compl	Build-Out Complete	
NAVSTA Newport	Micro	47	47	440	47	47	12/20/2001	4/26/2002	6/30/2003	1/15/2003			
Transformer: 480V in place. Ready for to	urnover to	EDS. EDS in	tends to upgra	ade to regiona	l server farm i	n FY04.							
NAVSHIPYARD Portsmouth, NH	Micro	298	298	170	298	298	12/18/2001	4/26/2002	7/30/2003	2/1/2003			
Transformer: 480V in place. Ready for tu	irnover to I	EDS. EDS sta	ates they will r	require second	floor only for	permanent fa	cilities, but wil	need entire b	building for tem	porary storage	э.		
NAS Brunswick	Micro	223	223	250	294	294	12/20/2001	4/26/2002	6/30/2003	8/15/2002			
Transformer: 480V in place. Ready for t	urnover to	EDS.						•					
SUBASE New London	Micro	433	433	433	433	433	11/12/2002	12/4/2002	6/30/2003	10/3/2003			
Transformer: 208V, 150 KVA in place, but	ut may req	uire upgradin	g some time ir	the future. S	tation needs to	remove asb	estos and pro	vide access ra	mp to facility /	ASAP.			
NWS Earle Mainside	Micro	C21	C21	N/A	C21	C21	7/12/2002	12/3/2002					
Transformer: existing transformer meets provided for upgrade to MSF.	current re	quirements. E	EDS to inform	Gov't if full site	e investigation	indicates add	ditional capaci	ty is required.	Two POPs al	ready installed	I. Sufficient sp	pace already	
NAVSTA Guantanamo Bay	TBD	2127	2127	752	834	834	11/6/2002						
Transformer available, but not installed.	Warehouse	e spaces to be	e changed to	B-834; new for	rmal offer lette	r pending. O	n "MSF pendi	ng" list.					
NAS JRB Willow Grove	Micro												
Transformer requirement not validated. N Warehouse at NSA Philadelphia B27A. N				quest for utility	/ easement is	being resolve	d with EFANE	Real Estate.	BAN/LAN spa	ace request ve	rbally approve	d.	
Philadelphia Naval Business Center	Micro	633	47	47	520		5/1/2003						
Transformer requirement not validated. I offered spaces. EDS questioning suitabil			ouse spaces o	offer letter sen	t to EDS 5/01/	03. Site visit	conducted on	5/15/03. Wai	ting for EDS si	te assessmen	t and accepta	nce of	
Pentagon	TBD	1D1070	1C1039	5D784	5B741	4A666					100%	1/16/2002	
Transformer: N/A. 2500 S. F. POP insta sufficient space. On "MSF pending" list.			dering combir	ning Navy and	Marine Corps	MSF at Penta	agon into sing	le facility, alon	g with Navy M	SF at Navy Ar	nnex. Appears	s to be	
Navy Annex	TBD												
Transformer: N/A. Space not available.	Should be	run out of Pe	entagon. On "	MSF pending"	list.								
Potomac Annex	TBD												
Transformer: N/A. On hold, BUMED act	ivity.												
NDW Anacostia Annex	TBD	A-072	A-168	A-150	A-168	A-150							
Transformer: existing transformer meets equipment. On "MSF pending" list. May			DS to inform	Gov't if full inv	estigation indi	cates addition	nal capacity is	required. Exp	panding curren	t POP would r	equire relocati	ing all	
NC Nebraska Ave	TBD	N-017	N-018	N-007	N-018	N-019							
Transformer: existing transformer meets equipment. On "MSF pending" list. May			DS to inform	Gov't if full inv	estigation indi	cates additior	nal capacity is	required. Exp	panding curren	t POP would r	equire relocati	ing all	

On Track	(	Outstanding Is	ssue	Difficulty				Change		Plan Actual		
Installation	Facility Size	Server	Perm Admin	Temp Admin	Perm Warehouse	Temp Warehouse	Bldg Offered	Bldg Accept	30% Design Review	Gov repair Complete	Constr. % Compl	Build-Out Complete
NMIC Suitland	TBD											
Fransformer: N/A. On hold, BUMED activity.												
NSWC Indian Head	Micro	290	290	289	290	290	11/15/2001	4/26/2002	6/30/2003	12/31/2002		
Transformer: 480V on site. Ready for turnover to EDS.												
NAF Washington	TBD	F-3086	F-3086	F-3086	F-3086	F-3086						
Transformer: existing transformer meets current requirements. EDS to inform Gov't if full investigation indicates additional capacity is required. POP facility operational and meeting all current demand Space may be expandable to MSF. On "MSF pending" list. May stay a POP.												nt demands.
NSWC Carderock	Micro	17	17	17	110	110	4/25/2003	5/27/2003	6/30/2003	7/15/2003		
Transformer: 480V service available. Server farm space ready for turnover to EDS. Station needs to perform some asbestos remediation work in Permanent admin spaces.												
NNMC Bethesda	TBD											
Transformer: N/A. BUMED on hold.												
Presidential Towers	TBD	CM1	CM1	N/A	Regional	Regional						
Transformer: N/A. Warehouse will be ru by ITA. EDS will have to build off their ba	n out of reackbone.	gional wareho Sufficient spac	ouse at NAF W ce exists in se	ashington. Le	eased space, In to accommo	EDS contacted date to MSF if	d owner for ap needed. On	proval of close "MSF pending	et spaces. Inf g" list. May sta	rastructure, in y a POP.	cluding server	farm owned
NSWC Dahlgren	Micro	423	423	1200	423	9411	2/5/2002	4/26/2002	7/30/2003	10/1/2002		
Transformer: 480V installed. Station and	DS reso	olving station	concern that N	ledium server	farm capabilit	ies may be ne	eded. Ready	for turnover t	o EDS.			
Dam Neck (NAS Oceana)	Micro	617	617	585	Regional	Regional	7/17/2002	7/23/2002	7/31/2003	11/25/2002		
Transformer: need verification of capacity	y requirem	ents prior to o	ordering transf	ormer. Existin	ng mezzanine	may need to b	e modified du	ring EDS build	d-out of space	. Ready for tu	rnover to EDS	).
Lafayette River Annex	Micro	Α	Α	Α	Regional	N/A			7/1/2003			
Transformer: existing transformer meets anticipated locating condenser units. Sta					estigation indi	cates addition	al capacity is	required. Spa	ace appears to	be sufficient t	for MSF. Som	e challenges
COMLANTFLT CMPD	М	NH-95	NH-95	NH-95	Regional	Regional	10/11/2002	10/24/2002	7/31/2003	9/2/2003		
Transformer: sufficient power is currently facility will be delayed.	available.	Space is su	fficient. EDS r	needs to provi	de SIPRnet co	nnectivity to a	another buildin	g to allow relo	ocation of exist	ing tenants, o	r turnover of s	erver farm
NWS Yorktown	TBD	376	466	NA	Regional	NA	4/26/2002					
Transformer: existing transformer meets expand to an MSF if needed. On "MSF p				Gov't if full inv	estigation indi	cates addition	al capacity is	required. Site	e visited 4/18/0	3. Appears to	be sufficient	space to
NMC Portsmouth	TBD											
Transformer: N/A. BUMED on hold.												
NAVSHIPYARD Portsmouth, VA	Micro	31	31	31	Regional	Regional	11/18/2001		7/30/2003	6/20/2003		
Transformer: 480V installed, running pov	ver to build	ling. Station	orovided temp	orary admin s	pace in Bldg 1	9 until work is	completed in	Bldg 31.				

On Track	Outstanding Issue			Difficulty				Change		Plan Actual		
Installation	Facility Size	Server	Perm Admin	Temp Admin	Perm Warehouse	Temp Warehouse	Bldg Offered	Bldg Accept	30% Design Review	Gov repair Complete	Constr. % Compl	Build-Out Complete
NAVFAC Engineering Southern Division	Micro	2155										
Existing 1800 KVA transformer is adequate requirements for admin and warehouse.	ite for the N	MSF. Site vis	it conducted o	n 4/29/03. Pla	anned POP sp	ace should a	ccommodate N	MSF equipme	nt. Space offe	r letter is need	led. EDS vali	dating
Dobbins ARB	TBD	30	30	30	305	305						
Transformer requirement not validated. Slist. May stay a POP for the Navy seats.	Site visit co	enducted on 5	/02/03. Existi	ng POP is ope	rational and s	hould accomn	nodate MSF e	quipment if ne	eded. Space	offer letter ne	eded. On "MS	SF pending"
SUBASE Kings Bay	Micro	4030	4030	2011	Regional	Regional	12/4/2001	4/12/2002		5/21/2002		
Power available, needs to be verified. All	l gov't facil	ities actions a	re complete a	nd ready for E	DS. New site	visit conducte	ed on 4/16/03.	Adequate sp	ace is availab	le. Waiting for	r EDS design.	
NAS Jacksonville	Regional	170	170	170	170	170	5/1/2002	6/4/2002				
Transformer to be installed 6/03. EDS havisit conducted on 4/15/03. Waiting for E			nt offer of spa	ice is adequate	e for the propo	sed Regional	Server Farm	at this installa	tion. Accepta	nce letter on fi	le is applicabl	e. New site
NAVSTA Mayport	Micro	192	192	192	Regional	Regional						
Transformer installed may be adequate.	EDS has r	not accepted E	3ldg 192. Nev	v site visit cond	ducted on 4/15	5/03. New off	er letter is nee	eded.				
NSWCDD Panama City	Micro	500	500		Leased	Leased	12/17/2001	10/1/2002				
Transformer requirement not validated. Nasace to Bldg 500.	New temp a	admin space i	needs to be id	entified. No pe	ermanent or te	emp warehous	se available. \	Waiting for ED	S design. Ne	w offer letter n	eeded to char	nge admin
NAS Pensacola	Micro	649	649	741/25	649	649	11/29/2001	4/29/2002				
New site visit conducted 4/17/03. EDS m	nay centrali	ize storage ar	nd imaging for	other installati	ions here. Sp	ace is adequa	ate for MSF. V	Vaiting for ED	S design.			
OLF Saufley Field	Micro	2434	2434	N/A	Regional	Regional						
Transformer installed Site visit conducted	on 4/17/0	<ol><li>Existing Position</li></ol>	OP can be mo	dified for MSF	. Offer letter i	s needed.						
NTTC Corry Station	Micro	502	502	502	Regional	Regional						
Transformer requirement not validated. S	Site visit co	nducted on 4	/17/03. Adequ	uate space is a	available. Offe	er letter is nee	ded.					
NAS Whiting Field	Micro	1415	1416	2998	Regional	2998						
Transformer requirement not validated. S	Site visit co	nducted on 4	/17/03. Adequ	uate space is a	available. Offe	er letter is nee	ded.					
NAS Key West	TBD	4011	4011	626/4011	4011	149	2/4/2002	4/26/2002				
Transformer may be adequate. Need to	verify 225 I	KVA at 208 V	. Space will b	e adequate for	MSF. On "M	SF pending" I	ist. May be de	ownsized to a	POP.			
NAS Meridian	Micro	224	224	266	224	224	12/18/2001	4/26/2002				
Transformer requirement not validated. Edesign.	Different BI	dg proposed t	for temp admi	n. New site vis	sit conducted	on 5/01/03. S	Space is adequ	uate for MSF.	Need revised	offer letter for	B-266. Waiti	ng for EDS
CBC, NCTC, NRC Gulfport	Micro	203	203	60/329	203	16	3/18/2002	4/26/2002				
Transformer installed. New site visit cond	ducted on 4	4/30/03. Assi	gned space is	adequate and	l available. W	aiting for EDS	design.					

On Track	Outstanding Issue			Difficulty				Change		Plan Actual			
Installation	Facility Size	Server	Perm Admin	Temp Admin	Perm Warehouse	Temp Warehouse	Bldg Offered	Bldg Accept	30% Design Review	Gov repair Complete	Constr. % Compl	Build-Out Complete	
Stennis Space Center	Micro	1210	1210	1210	9134	9134	8/12/2002	12/9/2002					
Transformer installed. Space offered and	daccepted	. New site vis	sit conducted 5	5/01/03. Assig	ned space is	adequate for I	MSF. Waiting	for EDS desig	gn.				
NS Pascagoula	Micro	10	10	10	70	70							
Transformer requirement not validated. I	New site vi	sit conducted	4/30/03. Ade	quate space is	available for	MSF, but adm	nin and wareh	ouse spaces v	vill be minimal	. Offer letter i	is needed.		
NTC Great Lakes	Micro	3400	3400	3400	3502	3502	11/1/2001	4/12/2002					
Space is adequate for MSF. Ready for E	DS turnov	er.											
SITC New Orleans	Micro	3	3	3	3	3							
Transformer probably not required. Site pending" list. May stay a POP.	visit condu	cted on 4/29/	03. Adequate	space is avail	able for MSF	(if needed) an	d Admin. Wa	rehouse space	e may be a pro	oblem. Offer I	letter is needed	d. On "MSF	
NSA New Orleans West Bank	TBD	102	71/266	71/266	71	706							
Transformer installed. Site visit conducte "MSF pending" list. May stay a POP.	ed on 4/29/	03. Adequate	space is avai	lable for MSF	(if needed) is	available in ex	xisting POP.	Admin and wa	rehouse is als	so available. (	Offer letter is n	eeded. On	
NAS JRB New Orleans	TBD	30	305	305	30	30							
450A transformer installed. Site visit con	ducted on	4/29/03. Ade	quate space is	s available for	MSF (if neede	ed), Admin, an	nd warehouse.	Offer letter is	s needed. On	"MSF pendin	g" list. May sta	ay a POP.	
Tinker AFB	Micro	825	825	825									
Need for transformer in question. Site vis space is being sought. Warehouse spac											entified. Addition	onal admin	
NAS JRB Fort Worth	Micro	1450	1430/1450	1430/1450	1402	1402							
Need to confirm existing transformer cap	acity. Site	visit conducte	ed 4/28/03. Ac	dequate space	is available fo	or MSF, Admir	n, and wareho	use. Offer let	ter is needed.				
NS Ingleside	Micro	100			27								
Transformer requirement not validated.	Site visit co	nducted 4/10	/03. Adequate	MSF and wa	rehouse space	e is available.	Station need	s to identify a	dmin space. C	Offer letter is n	needed.		
NAS Kingsville	Micro	2742	2742	2742	2742	2742							
Transformer to be ordered as part of buil	ding demo	project. Site	visit conducte	d 4/10/03. Ad	equate MSF,	admin and wa	rehouse spac	e is available.	Offer letter is	needed.			
NAS Corpus Christi	Micro	10	22	22	22	22	11/7/2001	11/26/2001		3/30/2002	2		
New transformer probably not needed. N	lew site vis	sit conducted	4/10/03. Base	is proposing	to locate MSF	in Bldg 10 in	lieu of 22, whi	ch appears ac	lequate. Offer	r letter for Bld	g 10 is needed		
NWS Seal Beach	Micro	123	123	123	124	122							
Existing POP has room for expansion to	Micro Serv	er Farm. Adr	nin space has	been identifie	d and is furnis	hed.							
SSC Old Towne	TBD	OT-1	N/A	N/A	12	12							
Warehouse in San Diego consolidated a	rea wareho	use. On "MS	F pending" lis	t. May stay a	POP. Admin	space at Poin	t Loma.						
Navy Broadway Complex San Diego	TBD												
Awaiting EDS results from site visit. On	"MSF pend	ding" list. May	stay a POP.				1						

On Track		Outstanding Issue Difficulty			Difficulty				Plan Actual			
Installation	Facility Size	Server	Perm Admin	Temp Admin	Perm Warehouse	Temp Warehouse	Bldg Offered	Bldg Accept	30% Design Review	Gov repair Complete	Constr. % Compl	Build-Out Complete
NMC San Diego	TBD											
BUMED on hold. Navy seats will be conr	nected to tr	ansport boun	dary POP.									
ASWTC San Diego	Micro	11			12	12						
POP space identified and is currently und	der constru	ction. Existing	g POP has en	ough space to	be expanded	into Micro Se	erver Farm. Ad	dmin is at Sub	ase. Consolic	lated warehou	se will be use	d.
NAVPHIBASE Coronado	Micro	16	16	401	12	12	5/14/2003					
Offer letter received 5/14/03. Consolidate	ed wareho	use will be us	ed. Need acc	eptance letter	from EDS.				l .			
NSWC Corona	Micro	509	509	513	509			1/7/2003				
Existing POP has room for expansion to	Micro Serv	er Farm. Per	m, Temp Adm	in, and Wareh	ouse spaces	are occupied	by EDS.		•			
NPGS Monterey	TBD	428	428	428	428	428						
Awaiting POP requirements from EDS. E	Electrical p	ower service o	could be a long	g lead item. S	pace is being	reconsidered	. On "MSF pe	nding" list. M	ay stay a POP			
PMRF Barking Sands	Micro											
Space requirements for MSF and associa	ated space	sent to PMRF	. Site visit be	ing scheduled	l.				•			
NAVSTA Everett	Micro	2200	2200	2000	2200	2200	12/27/2001	3/12/2002				
Space is ready for EDS turnover. Pre-co	n held 05 .	Jun 03.							•			
NAS Whidbey Island	Micro	219	113	113	2644	2670	12/27/2001	8/26/2002				
Pre-con held 04 Jun 03. EDS has reques	sted Bldg	976 in lieu of I	3ldg 219.						l .			
Puget Sound/Bremerton	Regional	922	922	434	922	1013	12/27/2001	8/12/2002		6/30/2002		
Downsized to Regional Server Farm. Sp	ace is read	dy for EDS tur	nover. Pre-co	n meeting hel	d 03 Jun 03.  [	Design sched	uled to be com	nplete 24 Jun	03.			
SUBASE Bangor	Micro	7074	1004	1004	922	1013	12/27/2001	6/13/2002				
Perm warehouse located in Bldg 922 at E	Bremerton.	Temp wareho	ouse located in	n Bldg 1013 at	Keyport. Faci	lities are read	ly for EDS turn	over. Pre-con	held 03 Jun 0	3.		